
9000# Jack Kit and Mtg/Tie Kit: Straight-Acting Jacks

Application: Mounting Straight-Acting Jacks on the REAR OF FORD, 2004 thru 2011 chassis with 19.5-22.5" TIRES.

Mfr. #: AP49761 9000# Rear Jack Kit	Mfr. #: 1 - AP49764 Mtg/Tie Kit 9S FD/WH
Includes: 2 - AP49759 Jack 9000x15 FXBA WS	Includes: 2 - AP48082 Mtg Brkt - 9S FDR THRD BO
	1 - AP48141 Clamp Kit 9S Mtg Outer
	1 - AP49765 Clamp Kit 9K CT THRU
	1 - AP16184 Hardware Kit 7/16"
	1 - P43079 Crosstie Inner 38" Formed
M.S.R.P.: See Item Price Listing	M.S.R.P.: See Item Price Listing

Note: this sheet is for 2004 thru 2011 chassis. 2004 motor homes may have a 2003 chassis. The 10th digit of the VIN code will be "3" 2003 chassis or "4" 2004 chassis.




INSTRUCTION SHEET STRAIGHT - ACTING MOUNTING BRACKET & CROSSTIE WITH CLAMPS


The jack mounting bracket has a small diameter clamp and a large diameter clamp. The small diameter clamp will only fit in a barrel groove. One or more grooves will be available near the top of the jack barrel. A different top groove may have to be used to achieve the proper mounting height. The clamp for the top groove is used to keep the jack at the proper mounting height and caries the entire vertical load for the jack. It is recommended to clamp the jack in the mounting bracket before installing the bracket. This will assist locating the bracket in the proper location and achieving the proper mounting height. Tack the bracket in place, remove the jack from the bracket if necessary to completely weld the bracket to the frame.

If the bracket is to be welded to the frame, follow proper welding procedures and it is recommended to contact the vehicle or chassis manufacturer for specific welding instructions.

The clamps are designed to allow slight clearance when fully tightened. This eliminates the possibility of any "squeeze" on the cylinder that could affect the operation of the jack. Check the jack grooves and the clamps for any debris that could cause a "squeeze" when the clamps are tightened. The jack can be slightly loose in the clamps with the clamps fully tightened.







MI25.9999 02OCT12