REMOTE SENSING UNIT CONVERSION
INSTRUCTION SHEET

FRONT VIEW OF BOX

P2455 STRAIN RELIEF

ASSEMBLE CONNECTOR
AFTER PULLING CABLE
THROUGH BOX

B-211-N BACK UP RING
PLACE ON BOTH SIDES
OF ENCLOSURE

WIRE END OF CONNECTOR

6

**NOTE: USE TOOL TS5054 TO
CRIMP WIRES ONTO CONNECTOR.**

6. WHITE
5. YELLOW
4. BLACK
3. GREEN
2. ORANGE
1. RED

1

CAUTION: Follow CAUTIONS in Operator's and Installation
Manuals concerning working under vehicles.

MI15.4753
14NOV08