

## PARKER MOTOR REPLACEMENT

NOTE: Do not prep replacement motor until ready to install.





TERMINALS ARE NUMBERED ON THE FACE OF THE MOTOR TIGHTEN TERMINAL NUTS TO 44 IN·LBS, MAX