

REPLACEMENT INSTRUCTIONS

3 WIRE MAGNETIC WARNING SWITCH FOR STRAIGHT-ACTING JACKS HARNESS WITH 1 WIRE AND SINGLE PIN PACKARD OR 2 WIRES WITH 2 PIN PACKARD

The sheet is used when replacing a 3 wire magnetic warning switch. The RAP37832 adaptor is not needed if the harness has one wire with a single pin Packard connector. The replacement switch will be a 2 wire warning switch with a single 2 pin Packard connector.

