



NOTE: HOSE ① IS INCLUDED WITH THE SYNC. CYLINDER.

- ④ HOSE ASSY 04
PRESSURE
- ③ 375' OD NYLON TUBING
RETURN
- ② HOSE ASSY 03
ROD END - ALWAYS PRESSURIZED - MUST BE HIGH PRESSURE HOSES OF EQUAL LENGTH AND DIAMETER
- ① HOSE ASSY 04
CAP END (LIFT)
- ① HOSE ASSY 03
CAP END (ROOM)
- ① HOSE ASSY 03
CAP END (ROOM)
- ① HOSE ASSY 03
ROD END (LIFT) - ALWAYS PRESSURIZED
- ② HOSE ASSY 03
CAP END (LIFT)
- ② HOSE ASSY 04
ROD END - ALWAYS PRESSURIZED (LIFT)
- ① HOSE ASSY 03
ROD END (LIFT) - ALWAYS PRESSURIZED
- ② HOSE ASSY 03
CAP END LIFT
- ① STEEL TUBE
CAP END (LIFT)

NOTE: INSTALLATION MUST CONFORM TO GOOD SHOP PRACTICES, SAE STANDARDS, RVIA STANDARDS, AND OTHER APPLICABLE STANDARDS.

NO.	DATE	REVISION

<p>THE INFORMATION DISCLOSED ON THIS DRAWING IS CONFIDENTIAL AND MUST NOT BE DISCLOSED OR USED IN ANY MANNER WHICH WILL BE DETRIMENTAL TO THE HWH CORPORATION</p>	<p>NEWMAR</p>	<p>DRAWING NUMBER MP71086</p>
---	---------------	-----------------------------------

*NOTE: ISOLATED PRESSURE IF AVAILABLE, SEE LEVELLING SYSTEM DIAGRAM

<p>HWH 1-80 EXIT 267 SOUTH RT 1 MOSCOW, IOWA 52760</p>	<p>SCALE 1:6 DATE 20FEB17 DRAWN BY</p>	<p>HYD CONN DIAGRAM</p>
--	--	-------------------------